


19. Unit Output Feedback Control


Here, we will introduce the simplest control scheme called the unit output feedback control and depicted in the following block diagram, where $H(s)$ is the transfer function of the plant to be controlled, K is the constant feedback control, $u(t)$ is the plant input, $y(t)$ is the plant output, y_d is the command or desired output, and $e(t)$ is error signal of $y(t)$ deviated from y_d .



For simplicity, let consider a second order plant as an example whose transfer function is given as below:

$$H(s) = \frac{cs + d}{s^2 + as + b} \quad (1)$$

With the Laplace transform, the total system can be redrawn as the following block diagram, where $U(s)$, $Y(s)$ and $E(s)$ are the Laplace transforms of input, output and error signal.



From the block diagram, the command $\frac{y_d}{s}$ is the input of the controlled system, the error is

$$E(s) = \frac{y_d}{s} - Y(s) \quad (2)$$

the input is

$$U(s) = KE(s) \quad (3)$$

and the output is

$$Y(s) = H(s)U(s) \quad (4)$$

From (2), (3) and (4), we obtain

$$Y(s) = H(s)U(s) = KH(s)E(s) = KH(s) \left(\frac{y_d}{s} - Y(s) \right) \quad (5)$$

and further rearranging it yields

$$Y(s) = \frac{KH(s)}{1 + KH(s)} \left(\frac{y_d}{s} \right) \quad (6)$$

From (1), we have

$$Y(s) = \frac{Kcs + Kd}{s^2 + (a + Kc)s + b + Kd} \left(\frac{y_d}{s} \right) \quad (7)$$


From the final value theorem, if the two roots of $s^2 + (a + Kc)s + b + Kd = 0$ are in the complex left-half plane, then for $t \rightarrow \infty$ the output will be

$$\begin{aligned} \lim_{t \rightarrow \infty} y(t) &= \lim_{s \rightarrow 0} sY(s) \\ &= \frac{(Kcs + Kd)y_d}{s^2 + (a + Kc)s + b + Kd} \Big|_{s=0} = \frac{Kd}{b + Kd} y_d \end{aligned} \quad (8)$$

It is obvious that if $b=0$, then the output can be successfully controlled to the desired output, i.e., $\lim_{t \rightarrow \infty} y(t) = y_d$, otherwise there exists a steady-state error.

On the other hand, if $c=0$ and $a < 0$, then the two roots can not be adjusted to the complex left-half plane. In other words, it is not controllable. Moreover, if $cd < 0$, c and d not with the same numeric sign, it will be more difficult to design the control gain K . A plant with $cd < 0$ is called a nonminimum plant.

Example: Motor vvelocity control



The structure of a DC motor is shown above, including the armature resistance R and winding leakage inductance L . The dynamic equation is

$$Ri_a(t) + L \frac{di_a(t)}{dt} + k\omega(t) = v_s(t) \quad (9)$$

$$J \frac{d\omega(t)}{dt} + B\omega(t) - ki_a(t) = 0 \quad (10)$$

where $i_a(t)$ is the armature current, $v_s(t)$ is the voltage source and $\omega(t)$ is the angular velocity. From (9) and (10), we have

$$J\ddot{\omega}(t) + \left(B + \frac{RJ}{L} \right) \dot{\omega}(t) + \left(\frac{BR}{L} + \frac{k^2}{L} \right) \omega(t) = \frac{k}{L} v_s(t) \quad (11)$$


which can be rewritten as

$$\ddot{\omega}(t) + a\dot{\omega}(t) + b\omega(t) = dv_s(t) \quad (12)$$

with $a = \frac{B}{J} + \frac{R}{L}$, $b = \frac{BR}{JL} + \frac{k^2}{JL}$ and $d = \frac{k}{JL}$. The transfer function is

$$H(s) = \frac{d}{s^2 + as + b} \quad (13)$$

In order to control the motor to move in a desired velocity ω_d , we use the unit output feedback control shown as below:



Then, the resulted output is

$$\Omega(s) = \frac{Kd}{s^2 + as + b + Kd} \left(\frac{\omega_d}{s} \right) \quad (14)$$

where the two roots of $s^2 + as + b + Kd = 0$ are in the complex left-half plane.

Hence, as $t \rightarrow \infty$ the output will be

$$\begin{aligned} \lim_{t \rightarrow \infty} y(t) &= \lim_{s \rightarrow 0} sY(s) \\ &= \left. \frac{Kd\omega_d}{s^2 + as + b + Kd} \right|_{s=0} = \frac{Kd}{b + Kd} \omega_d \end{aligned} \quad (15)$$

and a steady-state error exists.